Monsanto

DATE March 12, 1985

SUBJECT Status Report on CEA 3808

R. Lichtenheld - CS6G

R. Nelson

K. Petterson

O. Shipley

B. Steketee

TO

P. Hoemann

The joint east of ICC was retested and encased.

Encasement base at 1DD was poured.

Encasement bases for L34 and L35 were poured.

Excavation for 1GG in service road on south side of ACL was excavated.

VCP in 6", 8" 12", and 15" is on the job site, arrived last week.

Leaking isolated joint between 1BB and 1CC was repaired, will be water tested this week.

Plant changed out #4 pump again on Friday. The pump that was installed last week went to ground on all phases.

Tom Carrico Operation Foreman

skg

HGK 4084767